



TAPPING TRAPS

No. 4

VALVE FLANGE BOLT HOLES NOT CONCENTRIC WITH BORE OF VALVE

